

Katun Performance™ Drum Unit Rebuild Kit for use in

Sharp DX & MX-C310/C311/C401-series

Digital Copier/Printers

Katun PN: 43363 • OEM PN: N/A

Improve your profits with this high-quality Katun drum unit rebuild kit for these popular Sharp machines!



Note: Products shown represent Katun products in this category.

Katun is very pleased to announce the introduction of a drum unit rebuild kit for these current Sharp machine applications – representing an important addition to our growing color product portfolio. This Katun® drum unit rebuild kit provides OEM-equivalent performance at significant cost savings versus new OEM drum units.

Benefits:

◆ Cost-Per-Copy Savings

Choose Katun and significantly reduce your cost per copy on these machines and improve your overall profitability. There is no need to replace the entire drum unit when a new drum and drum cleaning blade is all that is needed.

◆ OEM-Equivalent Quality and Performance

Sharp dealers can expect OEM-equivalent performance, image quality and life from this Katun Performance™ drum unit rebuild kit, which has been tested and approved in Katun's state-of-the-art laboratory, meeting all the strict Katun Performance™ 360° Quality Certification requirements.

◆ Easy to Rebuild and Preserve the Environment

This drum unit rebuild kit allows the servicing dealer to rebuild used OEM drum units profitably while reducing environmental waste. The rebuild process is easy and can be completed in about 10 minutes or less. Instructions are included in the kit box.

Monochrome Model Overview (Monochrome applications use one black drum unit.)

OEM	Model Series	Speed (ppm)	Intro Date	Status
Sharp	MX-B380 P	38	July 2010	Discontinued
	MX-B381	38	August 2009	Discontinued
	MX-B382	38	December 2010	Current
	MX-B400	40	January 2010	Current
	MX-B401	40	March 2009	Current
	MX-B402	40	October 2010	Current

Color Model Overview (Color applications use four drum units: one black and three color.)

OEM	Model Series	Speed (ppm)	Intro Date	Status
Sharp	DX-C310	31	February 2009	Current
	DX-C311	31	February 2009	Current
	DX-C380	38	February 2009	Discontinued
	DX-C381	38	February 2009	Discontinued
	DX-C400	40	February 2009	Current
	DX-C401	40	February 2009	Current
	MX-C310	31	February 2009	Current
	MX-C311	31	November 2008	Current
	MX-C312	31	October 2012	Current
	MX-C380	38	January 2009	Discontinued
	MX-C381	38	November 2008	Current
	MX-C382	38	December 2010	Current
	MX-C400	40	January 2010	Current
	MX-C401	40	December 2008	Current
	MX-C402	40	October 2010	Current

Product Metrics

Metrics	OEM	Katun
Part Numbers	Black Drum Unit: MX-C40NRB, MX-C38GRB, MX-C38FRB, MX-C38ARB	Rebuild Kit: 43363
	Color Drum Unit: MX-C40NRS, MX-C38GRS, MX-C38FRS, MX-C38ARB	
Sell Unit	Priced and sold per drum unit	Priced and sold per rebuild kit
Kit Contents	N/A	(1) OPC Drum (1) Drum Cleaning Blade (1) Rebuild Instructions
Country of Origin	China	Kit assembled in USA
Photoreceptor Stated Life*	Black: 60,000 copies Color (CMY): 30,000 copies	Black: 60,000 copies Color (CMY): 30,000 copies

* Actual photoreceptor life may vary depending on machine application, machine condition and usage conditions.